

INSPECTION REPORT



End of contract

GENERAL INFO

File	309869
License plate	TE6060
Vehicle identification number	W1NKJ0FB5RF095284
Dossier	2023122009
Make	Mercedes GLC Coupé 220d 197 4M
Mileage	65446
First registration	24/10/2023
client availability date	01/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
67	Wing Front Left / Trim / Replace	N
237	Wing Front right / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
41	Windshield // Replace	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
116	Wing Rear Left // Polish	Y
134	Bumper Rear // Repair & Painting	N
154	Rear Bonnet // Repair & Painting	N
162	Roof // Painting	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
282	Bumper Rear / Trim Center / Replace	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch



Bumper Rear / Trim Center / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Smart Repair Small-scratch




Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Seat Rear Left // Repair-scratch





Wing Rear Right // Repair & Painting-dent




Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Bumper Rear // Repair & Painting-scratch + dent





Rear Bonnet // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Windshield // Replace-cracked




Roof // Painting-Chemical reaction



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wing Front right / Trim / Replace-scratch