

INSPECTION REPORT

End of contract



GENERAL INFO

File	320841
License plate	1XPU514
Vehicle identification number	VXEVFHKKL7016954
Dossier	2020013269
Make	Opel Viv.TD 90kW 31 L3H1 Edit.
Mileage	180161
First registration	02/03/2020
client availability date	25/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
64	Wing Front Left // Repair & Painting	N
93	Rocker Panel Left // Repair & Painting	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
213	Door Front Right // Painting	N
217	Door Front Right / Trim / Replace	N
891	Lettering Removal 15min	N
41	Windshield // Replace	Y
46	Windshield / Rear View Mirror / Replace	N
77	Side View Mirror Left / Shell / Replace Not Painted	Y
83	Door Front Left // Painting	Y
87	Door Front Left / Trim / Replace	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	N
137	Bumper Rear // Replace without painting	Y
163	Roof // Repair & Painting	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
290	Rear Loading Door Left // Smart Repair Small	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures






Bumper Rear // Replace without painting-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch




Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Rear Loading Door Left // Smart Repair Small-dent



Roof // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-bad repair



Windshield // Replace-cracked



Windshield / Rear View Mirror / Replace-missing



Interior Cleaning // Small-dirty



Door Front Left / Trim / Replace-bad position



Rocker Panel Left // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Lettering Removal 15min-



Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right // Painting-scratch