

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                               |
|-------------------------------|-------------------------------|
| File                          | 320584                        |
| License plate                 | 2ACK659                       |
| Vehicle identification number | VR3EFYHYCMJ577024             |
| Dossier                       | 2020353417                    |
| Make                          | Peugeot Part.1.5BHDi 102 L2 H |
| Mileage                       | 271400                        |
| First registration            | 18/02/2021                    |
| client availability date      | 20/08/2026                    |
| inspectionDate                | 26/08/2026                    |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | Y       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | N       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | Y       |        |





## DAMAGES

| Damages | Type                                             | Acceptable |
|---------|--------------------------------------------------|------------|
| 891     | Lettering Removal 15min                          | N          |
| 12      | Bumper Front // Smart Repair Large               | Y          |
| 19      | Bumper Front / Lower Cover Not Painted / Replace | Y          |
| 84      | Door Front Left // Repair & Painting             | Y          |
| 137     | Bumper Rear // Replace without painting          | Y          |
| 163     | Roof // Repair & Painting                        | N          |
| 174     | Light / Rear Right / Replace                     | N          |
| 213     | Door Front Right // Painting                     | Y          |
| 294     | Rear Loading Door Left // Repair & Painting      | N          |
| 304     | Rear Loading Door Right // Repair & Painting     | Y          |
| 412     | Seat Front Left / Bottom Coating / Replace       | N          |
| 564     | Dashboard // Replace Completely                  | Y          |
| 569     | Dashboard / Steering Wheel / Replace             | Y          |
| 860     | Interior Cleaning // Small                       | Y          |

## Damage Pictures



Door Front Right // Painting-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Replace without painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Door Front Left // Repair & Painting-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Roof // Repair & Painting-rust



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Seat Front Left / Bottom Coating / Replace-hole



Dashboard // Replace Completely-N comf / out of order



Lettering Removal 15min-