

INSPECTION REPORT


End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 314197 |
| License plate | XY4778 |
| Vehicle identification number | VR3USHNSSNJ662295 |
| Dossier | 2021342018 |
| Make | Peugeot 2008 1.2 PT 130 Allure |
| Mileage | 123182 |
| First registration | 18/07/2022 |
| client availability date | 01/06/2026 |
| inspectionDate | 04/06/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | N | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | N | |
| Registration certificate | | N | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | Y | |





DAMAGES

| Damages | Type | Acceptable |
|---------|---|------------|
| 16 | Bumper Front // Polish | Y |
| 19 | Bumper Front / Lower Cover Not Painted / Replace | Y |
| 35 | Front Bonnet // Polish | Y |
| 38 | Front Bonnet / Insulation / Replace | N |
| 84 | Door Front Left // Repair & Painting | Y |
| 89 | Door Front Left / Window / Replace | Y |
| 91 | Rocker Panel Left // Smart Repair Medium | N |
| 106 | Door Rear Left // Polish | Y |
| 134 | Bumper Rear // Repair & Painting | N |
| 159 | Rear Bonnet / Rear Window / Replace | Y |
| 161 | Roof // Smart Repair Medium | Y |
| 217 | Door Front Right / Trim / Replace | N |
| 236 | Wing Front right // Polish | Y |
| 282 | Bumper Rear / Trim Center / Replace | Y |
| 310 | Wheel Two Tone Front Left // Repair | N |
| 320 | Wheel Two Tone Rear Left // Repair | Y |
| 330 | Wheel Two Tone Rear Right // Repair | N |
| 431 | Seat Rear Left // Repair | Y |
| 551 | Central Console // Repair | N |
| 594 | Trunk Lid Interior Coating / Complete Panel / Replace | Y |
| 860 | Interior Cleaning // Small | N |

Damage Pictures



Door Front Left / Window / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Front // Polish-scratch




Wing Front right // Polish-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Front Bonnet // Polish-scratch





Rear Bonnet / Rear Window // Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Central Console // Repair-scratch



Seat Rear Left // Repair-scratch



Roof // Smart Repair Medium-dent



Bumper Rear // Repair & Painting-scratch + dent





Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Door Front Right / Trim / Replace-bad position