

INSPECTION REPORT



End of contract

GENERAL INFO

File	319618
License plate	2DEY680
Vehicle identification number	VXKFPHNLP1006692
Dossier	2022181073
Make	Opel Astra 1.2 81kW Business E
Mileage	54840
First registration	27/02/2023
client availability date	12/08/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
131	Bumper Rear // Smart Repair Medium	Y
161	Roof // Smart Repair Medium	Y
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
540	Interior // Repair 1	N
551	Central Console // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
621	Front Right Door Interior Coating // Repair	Y
634	Rear Left Door Interior Coating // Replace Completely	N
641	Rear Right Door Interior Coating // Repair	Y
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures



Bumper Rear // Smart Repair Medium-scratch




Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Central Console // Repair-scratch




Rear Right Door Interior Coating // Replace Completely-scratch



Front Right Door Interior Coating // Repair-scratch



Door Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Small-dent



Front Bonnet / Insulation / Replace-worn



Rear Right Door Interior Coating // Repair-bad position



Interior // Repair 1-hole