

INSPECTION REPORT

End of contract

GENERAL INFO

File	314131
License plate	1YVD908
Vehicle identification number	TMBAS9NPXM7039068
Dossier	2020135067
Make	Skoda Superb TDi 122 Style DSG
Mileage	103124
First registration	29/12/2020
client availability date	01/06/2026
inspectionDate	06/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	N
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
134	Bumper Rear // Repair & Painting	N
145	Back Side / Logo / Replace	N
150	Rear Bonnet // Smart Repair Small	Y
183	Wing Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
244	Light / Front Right / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
540	Interior // Repair 1	N
615	Front Left Door Interior Coating / Reflector / Replace	N


Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Wing Rear Right // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Rear Bonnet // Smart Repair Small-dent



Bumper Rear // Repair & Painting-scratch + dent



Front Left Door Interior Coating / Reflector / Replace-cracked



Back Side / Logo / Replace-missing




Headlight / Front left / Replace-Chemical reaction



Light / Front Right / Replace-Chemical reaction



Seat Front Left / Rear Coating / Replace-worn



Bumper Front // Painting-Chipped paint



Interior // Repair 1-hole