ARVAL
BNP PARIBAS GROUP

2AGC501

INSPECTION REPORT

End of contract

GENERAL INFO

File	306479
License plate	2AGC501
Vehicle identification number	W1K2050141R618651
Dossier	2020 118 067
Make	Mercedes C 220 d 143kW Aut.
Mileage	143187
First registration	24/03/2021
client availability date	09/03/2026
inspectionDate	11/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		Y	
Charging cable		N	
Charge back wrong tyres		N	

B
2 - AGC - 501

DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
14	Bumper Front // Repair & Painting	N
133	Bumper Rear // Painting	N
165	Roof // Polish	Y
194	Door Rear Right // Repair & Painting	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N

Damage Pictures



Damage within Renta-norm-

Wheel Two Tone Rear Left // Repair-scratch

Door Rear Right // Repair & Painting-scratch + dent

Bumper Front // Repair & Painting-scratch + dent

Seat Front Left / Bottom Coating / Replace-Incinerated

Wheel Two Tone Front Right // Repair-scratch

Wheel Two Tone Rear Right // Repair-scratch

Bumper Rear // Painting-scratch

Wheel Two Tone Front Left // Repair-scratch



Roof // Polish-scratch

Side View Mirror Right // Painting-scratch

Side View Mirror Right / Direction Indicator / Replace-scratch