ARVAL
BNP PARIBAS GROUP

2AEX580

INSPECTION REPORT

End of contract

GENERAL INFO

File	308820
License plate	2AEX580
Vehicle identification number	W1K1771841J304546
Dossier	2020237055
Make	Mercedes A Berline 180 Aut.
Mileage	86592
First registration	12/03/2021
client availability date	23/03/2026
inspectionDate	27/03/2026



CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	

13.0°C
14:06
0 km/h
0.0
84992
193 km

B
2 - AEX - 580

DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
274	Bumper Front / Grid Central / Replace	N
41	Windshield // Replace	N
75	Side View Mirror Left // Polish	Y
133	Bumper Rear // Painting	Y
183	Wing Rear Right // Painting	Y
208	Rocker Panel Right / Cover Not Painted / Replace	N
233	Wing Front right // Painting	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Rocker Panel Right / Cover Not Painted / Replace-cracked





Interior Cleaning // Small-stain

Wing Front right // Painting-scratch

Wheel Front Right / Wheel Cover / Replace-scratch

Wing Rear Right // Painting-scratch

Wheel Rear Right / Wheel Cover / Replace-scratch



Bumper Rear // Painting-scratch

Side View Mirror Left // Polish-scratch

Wheel Front Left / Wheel Cover / Replace-scratch

Windshield // Replace-scratch

Bumper Front // Repair & Painting-scratch + dent

Bumper Front / Grid Central / Replace-bad position