ARVAL
BNP PARIBAS GROUP

2ACB705

INSPECTION REPORT

End of contract

GENERAL INFO

File	306906
License plate	2ACB705
Vehicle identification number	YV1UZK5VDM1813690
Dossier	2020 254 036
Make	Volvo XC60 B4 D Momentum Pro G
Mileage	160587
First registration	16/02/2021
client availability date	02/03/2026
inspectionDate	12/03/2026



CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	

B
2 - ACB - 705

DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
66	Wing Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
151	Rear Bonnet // Smart Repair Medium	N
196	Door Rear Right // Polish	Y
205	Rocker Panel Right // Polish	Y
216	Door Front Right // Polish	Y
631	Rear Left Door Interior Coating // Repair	N
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures

Damage within Renta-norm-scratch




Bumper Rear // Polish-scratch





Door Rear Left // Polish-scratch

Wing Front Left // Polish-scratch



Front Bonnet // Polish-scratch

Rocker Panel Right // Polish-scratch



Door Front Right // Polish-scratch

Rear Left Door Interior Coating // Repair-dent

Rocker Panel Left // Smart Repair Medium-scratch + dent



Rear Bonnet // Smart Repair Medium-scratch + dent

Door Rear Right // Polish-bad repair



Windshield // Repair-cracked

Interior / Side Cover rear Seat / Replace-hole