

INSPECTION REPORT

End of contract

GENERAL INFO

File	314778
License plate	2APT978
Vehicle identification number	W1N2539111V284337
Dossier	2020 273 116
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	134050
First registration	04/06/2021
client availability date	10/06/2026
inspectionDate	30/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
18	Bumper Front / Spoiler / Replace	N
233	Wing Front right // Painting	N
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
221	Side View Mirror Right // Plastic Repair	N
228	Side View Mirror Right / Direction Indicator / Replace	N
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	N
113	Wing Rear Left // Painting	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	N
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	Y
196	Door Rear Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y

Damage Pictures



Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch



Bumper Rear // Painting-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet // Polish-scratch



Door Front Left // Smart Repair Medium-scratch





Rear Bonnet / Rear Window / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Rear Left // Smart Repair Medium-scratch + dent



Windshield // Repair-cracked




Wing Rear Right / Trim / Replace-bad position



Wheel Two Tone Front Right // Repair-scratch



Wing Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front right // Painting-scratch



Wing Front right / Trim / Replace-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-
scratch