

INSPECTION REPORT


End of contract

GENERAL INFO

File	304253
License plate	2CEN083
Vehicle identification number	TMAJE812DNJ098370
Dossier	2022 160 066
Make	Hyundai Tuc.TGDi PHEV 195kW 4x
Mileage	138197
First registration	24/06/2022
client availability date	24/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
340	Wheel Two Tone Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
881	Key Price Range 1 //	Y

Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch





Door Rear Right // Painting-scratch




Rocker Panel Left // Smart Repair Medium-scratch + dent




Windshield // Repair-glass damage



Door Front Left / Trim / Replace-worn



Door Front Left // Smart Repair Medium-worn



Seat Front Left / Rear Coating / Replace-worn



Front Left Door Interior Coating // Replace Completely-worn



Dashboard / Steering Wheel / Replace-worn



Key Price Range 1 //-worn