

INSPECTION REPORT


End of contract


GENERAL INFO

File	316497
License plate	1WSN817
Vehicle identification number	WDD2470031J046511
Dossier	2019 065 178
Make	Mercedes B 180 d Aut.
Mileage	155030
First registration	30/08/2019
client availability date	02/07/2026
inspectionDate	03/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
35	Front Bonnet // Polish	Y
44	Windshield / Trim / Replace	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
86	Door Front Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
116	Wing Rear Left // Polish	Y
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	Y
162	Roof // Painting	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
548	Interior / Side Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Roof // Painting-scratch





Rear Bonnet // Polish-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Door Rear Right // Polish-scratch



Door Front Right // Painting-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch




Bumper Front // Smart Repair Large-scratch



Windshield / Trim / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Left // Polish-scratch



Wing Rear Left // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch




Bumper Rear // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Left // Painting-bad repair



Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Small-stain