

INSPECTION REPORT

End of contract

GENERAL INFO

File	314871
License plate	2CDQ305
Vehicle identification number	VF3MRHNSUNS075776
Dossier	2021052002
Make	Peugeot 3008 1.2PTech 96kW GT
Mileage	48221
First registration	15/06/2022
client availability date	23/06/2026
inspectionDate	30/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
180	Wing Rear Right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Smart Repair Small-dent



Seat Front Left / Bottom Coating / Replace-worn