

INSPECTION REPORT


End of contract


GENERAL INFO

File	316258
License plate	2DAD729
Vehicle identification number	W1K5M8EB1PN362151
Dossier	2022 230 086
Make	Mercedes CLA SB 180 Luxury Lin
Mileage	65903
First registration	12/01/2023
client availability date	26/06/2026
inspectionDate	30/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
124	Light / Rear left / Replace	N
133	Bumper Rear // Painting	N
13	Bumper Front // Painting	Y
41	Windshield // Replace	Y
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
202	Rocker Panel Right // Painting	Y
233	Wing Front right // Painting	Y
244	Light / Front Right / Replace	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Polish-dent



Roof // Smart Repair Medium-dent



Dashboard / Steering Wheel / Replace-worn



Door Rear Right // Polish-scratch



Rocker Panel Right // Painting-scratch



Wing Front right // Painting-scratch



Light / Front Right / Replace-scratch



Bumper Front // Painting-scratch



Windshield // Replace-scratch



Wing Front Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch