

INSPECTION REPORT




End of contract

GENERAL INFO

File	316048
License plate	2CBK810
Vehicle identification number	W0VZCYHZXN6814909
Dossier	2021 208 109
Make	Opel Grandland X 1.5D 96kW Bus
Mileage	70272
First registration	20/05/2022
client availability date	23/06/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
165	Roof // Polish	Y
431	Seat Rear Left // Repair	Y


Damage Pictures




Seat Rear Left // Repair-scratch



Bumper Front // Polish-scratch



Roof // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent