

INSPECTION REPORT


End of contract

GENERAL INFO

File	316931
License plate	2ECR326
Vehicle identification number	VF3VFEHS7P7817825
Dossier	2022 209 128
Make	Peugeot Expert 2.0BHDi 145 Sta
Mileage	50551
First registration	30/08/2023
client availability date	01/07/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
110	Wing Rear Left // Smart Repair Small	N
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	N
196	Door Rear Right // Polish	Y
197	Door Rear Right / Trim / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
293	Rear Loading Door Left // Painting	Y
301	Rear Loading Door Right // Smart Repair Medium	Y
540	Interior // Repair 1	N

Damage Pictures



Rear Loading Door Left // Painting-scratch



Light / Rear Right / Replace-scratch



Door Rear Right / Trim / Replace-scratch




Door Rear Right // Polish-scratch



Door Front Right // Painting-scratch



Bumper Front // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Door Front Left / Trim / Replace-scratch




Wing Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Rear Loading Door Right // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior // Repair 1-hole