

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	307722
License plate	2BRQ951
Vehicle identification number	VF3MCYHZUNS038170
Dossier	2021 293 087
Make	Peugeot 5008 1.5BHdi 96kW GT A
Mileage	150377
First registration	28/02/2022
client availability date	17/03/2026
inspectionDate	07/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
125	Light / Rear Left On Rear Bonnet / Replace	Y
157	Rear Bonnet / Trim / Replace	Y
13	Bumper Front // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	N
217	Door Front Right / Trim / Replace	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
860	Interior Cleaning // Small	Y

## Damage Pictures







Damage within Renta-norm-




Light / Rear left / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Rear // Polish-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Front Right // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Right // Painting-bad repair



Interior Cleaning // Small-stain



Rear Bonnet / Trim / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch