

INSPECTION REPORT

End of contract

GENERAL INFO

File	320824
License plate	2CLA312
Vehicle identification number	VR3FCYHZTNY587186
Dossier	2021335085
Make	Peugeot 308 SW 1.5BHDi 130 All
Mileage	135453
First registration	31/08/2022
client availability date	24/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
13	Bumper Front // Painting	N
274	Bumper Front / Grid Central / Replace	N
801	See External Expertise	N
891	Lettering Removal 15min	N
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	Y
103	Door Rear Left // Painting	N
114	Wing Rear Left // Repair & Painting	Y
136	Bumper Rear // Polish	Y
139	Bumper Rear / Spoiler / Replace	N
184	Wing Rear Right // Repair & Painting	N
190	Door Rear Right // Smart Repair Small	Y
214	Door Front Right // Repair & Painting	Y
231	Wing Front right // Smart Repair Medium	N
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
548	Interior / Side Cover / Replace	Y
551	Central Console // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N


Damage Pictures



Bumper Rear / Spoiler / Replace-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Door Rear Left // Painting-bad repair



Interior Cleaning // Small-stain



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover / Replace-scratch



Wing Rear Left // Repair & Painting-dent



Wing Front right // Smart Repair Medium-dent




Door Rear Right // Smart Repair Small-dent



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Central Console // Repair-scratch



Bumper Rear // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch




Side View Mirror Left / Direction Indicator / Replace-scratch







Side View Mirror Left // Painting-scratch



Lettering Removal 15min-Remainder stickers





See External Expertise-dent



Bumper Front / Grid Central / Replace-scratch



Bumper Front // Painting-scratch