

INSPECTION REPORT


End of contract

GENERAL INFO

File	322328
License plate	2BGN100
Vehicle identification number	TMBJP7NXXNY035541
Dossier	2021 074 140
Make	Skoda Oct.Com.1.0 eTec 81kW Cl
Mileage	179291
First registration	17/11/2021
client availability date	18/09/2026
inspectionDate	29/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
174	Light / Rear Right / Replace	N
183	Wing Rear Right // Painting	N
16	Bumper Front // Polish	Y
33	Front Bonnet // Repair & Painting	Y
41	Windshield // Replace	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
110	Wing Rear Left // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
621	Front Right Door Interior Coating // Repair	N
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Front // Polish-scratch



Windshield // Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Front Right Door Interior Coating // Repair-scratch



Wing Rear Left // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent



Door Rear Right // Repair & Painting-scratch + dent




Door Front Right // Repair & Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Side View Mirror Left / Direction Indicator / Replace-cracked



Roof // Polish-Chemical reaction



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right / Replace-scratch



Wing Rear Right // Painting-scratch