

INSPECTION REPORT


End of contract

GENERAL INFO

File	315138
License plate	2BEM753
Vehicle identification number	VR3UDYHZSMJ858504
Dossier	2021 113 090
Make	Peugeot 2008 1.5BlueHDi 96kW A
Mileage	43560
First registration	22/10/2021
client availability date	20/06/2026
inspectionDate	23/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	N
237	Wing Front right / Trim / Replace	N
66	Wing Front Left // Polish	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
181	Wing Rear Right // Smart Repair Medium	Y
193	Door Rear Right // Painting	Y
213	Door Front Right // Painting	Y
282	Bumper Rear / Trim Center / Replace	Y
340	Wheel Two Tone Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N

Damage Pictures



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch




Wing Front Left // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Smart Repair Medium-scratch




Bumper Rear / Trim Center / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Polish-scratch



Trunk Compartment / Boot Cover / Replace-missing



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wing Front right / Trim / Replace-Chemical reaction