

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	311412
License plate	2EVJ995
Vehicle identification number	VR3F3DGXTPY684039
Dossier	2023 175 274
Make	Peugeot 408 1.6 180PHEV GT A
Mileage	33093
First registration	09/02/2024
client availability date	24/04/2026
inspectionDate	30/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
72	Side View Mirror Left // Painting	N
156	Rear Bonnet // Polish	Y
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

## Damage Pictures



Side View Mirror Left // Painting-scratch



Rear Bonnet // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Door Rear Right / Trim / Replace-scratch




Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-cracked



Front Bonnet / Insulation / Replace-cracked