

INSPECTION REPORT





End of contract

GENERAL INFO

File	319373
License plate	2BRE119
Vehicle identification number	W1N2539111G043926
Dossier	2021 168 080
Make	Mercedes GLC 300de 4M Bus.Sol.
Mileage	134492
First registration	22/02/2022
client availability date	03/08/2026
inspectionDate	11/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	Y
191	Door Rear Right // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	N
340	Wheel Two Tone Front Right // Repair	Y


Damage Pictures



Front Bonnet // Painting-scratch



Wing Rear Left / Trim / Replace-scratch



Bumper Rear // Painting-scratch




Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Smart Repair Medium-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent