

INSPECTION REPORT

End of contract

GENERAL INFO

File	317159
License plate	GH0625
Vehicle identification number	W1K1186141N296910
Dossier	2021356002
Make	Mercedes CLA SB 220d 190 AMG L
Mileage	147445
First registration	24/06/2022
client availability date	02/07/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	N
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
27	Front / Logo / Replace	Y
31	Front Bonnet // Smart Repair Small	Y
41	Windshield // Replace	N
63	Wing Front Left // Painting	N
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	N
125	Light / Rear Left On Rear Bonnet / Replace	N
136	Bumper Rear // Polish	Y
148	Back Side / Reflector R / Replace	Y
150	Rear Bonnet // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
196	Door Rear Right // Polish	Y
205	Rocker Panel Right // Polish	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
540	Interior // Repair 1	N
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Roof // Smart Repair Medium-dent



Door Front Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Front Bonnet // Smart Repair Small-dent



Rear Bonnet // Smart Repair Small-dent




Wing Rear Left // Repair & Painting-scratch + dent



Wing Front Left // Painting-bad repair



Windshield // Replace-glass damage



Roof // Polish-Chemical reaction



Trunk Compartment / Side Cover Left / Replace-tear



Front / Logo / Replace-Chipped paint



Interior // Repair 1-hole



Bumper Rear // Polish-scratch



Back Side / Reflector R / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch




Wing Rear Right // Painting-scratch




Door Rear Right // Polish-scratch



Rocker Panel Right // Polish-scratch



Door Front Right // Polish-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front / Spoiler / Replace-scratch