

INSPECTION REPORT

End of contract

GENERAL INFO

File	312909
License plate	2BFL617
Vehicle identification number	TMBJP7NX7NY034282
Dossier	2021049012
Make	Skoda Oct.Com.1.0TSI 81kW Clev
Mileage	155520
First registration	03/11/2021
client availability date	21/05/2026
inspectionDate	13/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N


Damage Pictures



Bumper Rear // Polish-scratch



Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Rear Right // Smart Repair Small-scratch + dent



Windshield // Repair-glass damage