

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	314032
License plate	XY4783
Vehicle identification number	VR3USHNSSNJ662272
Dossier	2021342045
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	77050
First registration	30/06/2022
client availability date	29/05/2026
inspectionDate	02/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	N
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
282	Bumper Rear / Trim Center / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
634	Rear Left Door Interior Coating // Replace Completely	N
860	Interior Cleaning // Small	N

## Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch




Light / Rear Right / Replace-scratch



Door Front Right // Polish-scratch



Wing Front right // Polish-scratch



Front Bonnet // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch




Door Front Left / Trim / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Door Front Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Left // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction



Interior Cleaning // Small-stain