

INSPECTION REPORT

End of contract

GENERAL INFO

File	307578
License plate	2EAA956
Vehicle identification number	YV1ZWBMUDL1350867
Dossier	2018323237
Make	Volvo V60 T8 PHEV Inscription
Mileage	179857
First registration	05/07/2019
client availability date	13/03/2026
inspectionDate	25/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
274	Bumper Front / Grid Central / Replace	N
114	Wing Rear Left // Repair & Painting	Y
190	Door Rear Right // Smart Repair Small	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Damage within Renta-norm-



Wing Rear Left // Repair & Painting-scratch + dent



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Smart Repair Small-dent



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Grid Central / Replace-scratch + dent