

INSPECTION REPORT


End of contract

GENERAL INFO

File	318828
License plate	1YQP707
Vehicle identification number	TMBJG7NP1M7010273
Dossier	2020015159
Make	Skoda Sup.Comb.TDi 120 Amb.DSG
Mileage	147656
First registration	09/11/2020
client availability date	30/07/2026
inspectionDate	05/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12 Bumper Front // Smart Repair Large		N
83 Door Front Left // Painting		Y
93 Rocker Panel Left // Repair & Painting		N
133 Bumper Rear // Painting		Y
203 Rocker Panel Right // Repair & Painting		N


Damage Pictures



Door Front Left // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Bumper Rear // Painting-scratch



Rocker Panel Right // Repair & Painting-scratch + dent



Rocker Panel Left // Repair & Painting-scratch + dent