

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	307395
License plate	2AWX704
Vehicle identification number	KMHC851CGMU247094
Dossier	2021161076
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	118990
First registration	23/08/2021
client availability date	10/03/2026
inspectionDate	12/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES



Damages	Type	Acceptable
153	Rear Bonnet // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	Y
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	N
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
222	Side View Mirror Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
421	Seat Front Right // Repair	Y
538	Trunk Compartment / Boot Cover / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
641	Rear Right Door Interior Coating // Repair	N
883	Key Price Range 2 //	N

## Damage Pictures






Damage within Renta-norm-scratch



Bumper Rear // Painting-scratch






Dashboard / Steering Wheel / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Rear Left // Painting-bad repair



Windshield // Replace-cracked



Front Bonnet / Insulation / Replace-cracked



Trunk Compartment / Boot Cover / Replace-missing



Front Bonnet // Painting-scratch




Bumper Front / Spoiler / Replace-scratch



Bumper Front // Painting-scratch




Seat Front Right // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch





Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Painting-scratch