

INSPECTION REPORT

End of contract


GENERAL INFO

File	321225
License plate	RA1092
Vehicle identification number	W1K5J1CB1PN326172
Dossier	2022222003
Make	Mercedes CLA 200d 150 AMG Line
Mileage	140286
First registration	29/08/2022
client availability date	01/09/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	N
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
208	Rocker Panel Right / Cover Not Painted / Replace	N
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
326	Tyre Rear Left // Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Rocker Panel Right / Cover Not Painted / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Left / Replace-scratch




Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch




Door Rear Left // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Roof // Smart Repair Medium-dent



Wing Rear Right // Repair & Painting-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Repair-glass damage



Tyre Rear Left // Replace-tear



Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain