

INSPECTION REPORT


End of contract

GENERAL INFO

File	318613
License plate	2CBL091
Vehicle identification number	VF3MCYHZUNS087172
Dossier	2021 344 040
Make	Peugeot 3008 1.5BHDi 96kW Allu
Mileage	92493
First registration	20/05/2022
client availability date	06/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
75	Side View Mirror Left // Polish	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
67	Wing Front Left / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
216	Door Front Right // Polish	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Front Left / Trim / Replace-bad position



Wheel Two Tone Front Right // Repair-scratch




Door Front Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Side View Mirror Left // Polish-scratch