

INSPECTION REPORT

End of contract

GENERAL INFO

File	318273
License plate	2DSF119
Vehicle identification number	YV1ZWK7V0R2610866
Dossier	2022270070
Make	Volvo V60 B3 Essential DCT
Mileage	99248
First registration	09/06/2023
client availability date	22/07/2026
inspectionDate	30/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
146	Back Side / Reflector L / Replace	N
14	Bumper Front // Repair & Painting	N
233	Wing Front right // Painting	N
72	Side View Mirror Left // Painting	Y
100	Door Rear Left // Smart Repair Small	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	N
139	Bumper Rear / Spoiler / Replace	N
154	Rear Bonnet // Repair & Painting	N
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	Y
213	Door Front Right // Painting	Y
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
551	Central Console // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
773	Interior / A Pillar Lower Cover / Replace	N
860	Interior Cleaning // Small	Y

Damage Pictures



Side View Mirror Left // Painting-scratch



Wing Rear Right // Polish-scratch



Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Central Console // Repair-scratch



Seat Front Right // Repair-scratch



Door Rear Left // Smart Repair Small-dent



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent




Rear Bonnet // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Interior / A Pillar Lower Cover / Replace-hole



Bumper Rear / Spoiler / Replace-scratch




Light / Rear left / Replace-scratch



Door Front Right // Painting-scratch



Back Side / Reflector L / Replace-scratch





Bumper Rear // Repair & Painting-cracked



Wing Front right // Painting-scratch



Bumper Front // Repair & Painting-scratch