

INSPECTION REPORT


End of contract

GENERAL INFO

File	320363
License plate	2AQX432
Vehicle identification number	VF3MCYHZMMS149333
Dossier	2020329014
Make	Peugeot 5008 1.5BHDi 96kW Acti
Mileage	210759
First registration	16/06/2021
client availability date	17/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
132	Bumper Rear // Smart Repair Large	N
181	Wing Rear Right // Smart Repair Medium	N
187	Wing Rear Right / Trim / Replace	N
891	Lettering Removal 15min	N
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
104	Door Rear Left // Repair & Painting	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	N
190	Door Rear Right // Smart Repair Small	N
228	Side View Mirror Right / Direction Indicator / Replace	N
311	Wheel Alloy Front Left // Repair	N
553	Central Console / Gear Lever / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet // Polish-scratch



Light / Rear Right / Replace-scratch



Windshield // Repair-glass damage



Interior Cleaning // Small-stain



Central Console / Gear Lever / Replace-worn



Side View Mirror Right / Direction Indicator / Replace-scratch



Front Bonnet // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Left // Repair & Painting-dent



Door Rear Right // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Medium-scratch



Wing Rear Right / Trim / Replace-scratch



Bumper Rear // Smart Repair Large-scratch + dent



Lettering Removal 15min-