

INSPECTION REPORT

End of contract

GENERAL INFO

File	311836
License plate	2CAC855
Vehicle identification number	W1K1186101N301972
Dossier	2021064107
Make	Mercedes CLA SB 180 d Bus.Sol.
Mileage	103249
First registration	06/05/2022
client availability date	29/04/2026
inspectionDate	08/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
100	Door Rear Left // Smart Repair Small	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Bumper Rear // Painting-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Smart Repair Small-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-Chemical reaction