

INSPECTION REPORT



End of contract

GENERAL INFO

File	320766
License plate	2BWV755
Vehicle identification number	W1K1771101J363250
Dossier	2021349265
Make	Mercedes A Berline 180 d Bus.S
Mileage	104746
First registration	22/04/2022
client availability date	26/08/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
257	Front / Towing Cover / Replace	N
40	Windshield // Repair	Y
103	Door Rear Left // Painting	Y
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
569	Dashboard / Steering Wheel / Replace	Y

Damage Pictures



Bumper Rear / Spoiler / Replace-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Windshield // Repair-cracked



Wheel Two Tone Rear Right // Repair-Chemical reaction




Dashboard / Steering Wheel / Replace-worn



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Painting-scratch



Side View Mirror Right // Painting-scratch



Rocker Panel Right // Smart Repair Medium-dent



Front / Towing Cover / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent