

INSPECTION REPORT





End of contract


GENERAL INFO

File	316125
License plate	NN4785
Vehicle identification number	W1K1770861N243857
Dossier	2021 090 068
Make	Mercedes A 250 e 160 Bus Sol A
Mileage	94177
First registration	17/06/2021
client availability date	24/06/2026
inspectionDate	26/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	N
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	N
203	Rocker Panel Right // Repair & Painting	Y
213	Door Front Right // Painting	N
222	Side View Mirror Right // Painting	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Bumper Front // Painting-scratch




Side View Mirror Right // Painting-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Front Bonnet // Polish-scratch



Rocker Panel Right // Repair & Painting-dent



Wing Rear Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent