

INSPECTION REPORT

End of contract

GENERAL INFO

File	320253
License plate	2BBW692
Vehicle identification number	W0VZ4DGZ3MS052150
Dossier	2021153022
Make	Opel Grand.X 1.6 225 Hybrid2 E
Mileage	150187
First registration	24/09/2021
client availability date	20/08/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
71	Side View Mirror Left // Plastic Repair	N
72	Side View Mirror Left // Painting	N
221	Side View Mirror Right // Plastic Repair	N
222	Side View Mirror Right // Painting	N
132	Bumper Rear // Smart Repair Large	N
184	Wing Rear Right // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
81	Door Front Left // Smart Repair Medium	N
87	Door Front Left / Trim / Replace	Y
106	Door Rear Left // Polish	Y
119	Wing Rear Left / Window / Replace	Y
137	Bumper Rear // Replace without painting	N
210	Door Front Right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
534	Trunk Compartment / Carpet / Replace	Y
544	Interior / Floor Covering / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N


Damage Pictures




Door Front Left / Trim / Replace-scratch



Wing Rear Left / Window / Replace-scratch



Bumper Rear // Replace without painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch




Door Front Right // Smart Repair Small-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Door Front Left // Smart Repair Medium-scratch + dent



Interior Cleaning // Small-dirty



Front Left Door Interior Coating // Replace Completely-worn



Interior / Floor Covering / Replace-worn



Dashboard / Steering Wheel / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn




Trunk Compartment / Carpet / Replace-worn




Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Polish-scratch



Front Bonnet // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch




Door Rear Left // Polish-scratch



Side View Mirror Left // Plastic Repair-scratch






Side View Mirror Left // Painting-scratch




Side View Mirror Right // Plastic Repair-scratch




Side View Mirror Right // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Smart Repair Large-scratch



Wing Rear Right / Trim / Replace-scratch