

INSPECTION REPORT


End of contract

GENERAL INFO

File	310270
License plate	2BTS524
Vehicle identification number	W1K1183861N301588
Dossier	2021181008
Make	Mercedes CLA 250 e Bus.Solut.A
Mileage	58439
First registration	18/03/2022
client availability date	22/04/2026
inspectionDate	04/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
14	Bumper Front // Repair & Painting	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
89	Door Front Left / Window / Replace	Y
110	Wing Rear Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
244	Light / Front Right / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
543	Interior // Ionization Odor	Y
544	Interior / Floor Covering / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch




Light / Front Right / Replace-scratch



Door Front Left / Window / Replace-scratch



Rear Bonnet // Polish-scratch





Bumper Rear // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch




Side View Mirror Left // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Interior / Side Cover rear Seat / Replace-scratch



Wing Rear Left // Smart Repair Small-dent



Door Front Left // Smart Repair Small-dent





Roof // Smart Repair Medium-dent








Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Front // Repair & Painting-scratch + dent




Interior / Floor Covering / Replace-Incinerated



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Wing Rear Right // Polish-scratch




Door Rear Right // Polish-scratch



Door Front Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch