

INSPECTION REPORT

End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 312625 |
| License plate | 2BXD881 |
| Vehicle identification number | W1K2470861J382763 |
| Dossier | 2021 265 080 |
| Make | Mercedes B 250 e PHEV Bus.Sol. |
| Mileage | 56773 |
| First registration | 27/04/2022 |
| client availability date | 13/05/2026 |
| inspectionDate | 22/05/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | Y | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | Y | |
| Registration certificate | | Y | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | Y | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|--|------------|
| 31 | Front Bonnet // Smart Repair Small | N |
| 91 | Rocker Panel Left // Smart Repair Medium | N |
| 133 | Bumper Rear // Painting | Y |
| 860 | Interior Cleaning // Small | N |

Damage Pictures



Bumper Rear // Painting-scratch



Front Bonnet // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Interior Cleaning // Small-stain