

INSPECTION REPORT

End of contract


GENERAL INFO

File	315697
License plate	JV5932
Vehicle identification number	VR3USHN5SNJ662335
Dossier	2021342108
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	63551
First registration	26/07/2022
client availability date	18/06/2026
inspectionDate	24/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
64	Wing Front Left // Repair & Painting	N
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
103	Door Rear Left // Painting	Y
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Left / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Painting-scratch



Door Rear Right // Polish-scratch



Door Front Right / Trim / Replace-scratch



Wing Front Left // Repair & Painting-dent



Door Front Right // Repair & Painting-dent



Wing Rear Right // Repair & Painting-dent



Interior Cleaning // Small-stain