

INSPECTION REPORT


End of contract

GENERAL INFO

File	316362
License plate	2CLT056
Vehicle identification number	VR3FCYHZLNY572009
Dossier	2022 238 044
Make	Peugeot 308 SW 1.5BHDi 130 All
Mileage	200113
First registration	08/09/2022
client availability date	02/07/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
27	Front / Logo / Replace	N
28	Front / Calendar / Replace	N
114	Wing Rear Left // Repair & Painting	N
131	Bumper Rear // Smart Repair Medium	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
203	Rocker Panel Right // Repair & Painting	N
216	Door Front Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	N
549	Interior / Headliner/ Replace	N
554	Central Console // Replace Completely	Y
569	Dashboard / Steering Wheel / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	Y

Damage Pictures







Trunk Lid Interior Coating / Complete Panel / Replace-cracked



Interior / Headliner/ Replace-Incinerated



Interior // Repair 1-Incinerated



Interior Cleaning // Small-dirty



Seat Front Left / Bottom Coating / Replace-worn



Central Console // Replace Completely-worn



Dashboard / Steering Wheel / Replace-worn



Wheel Two Tone Front Left // Repair-scratch




Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch




Bumper Rear // Smart Repair Medium-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Repair & Painting-scratch



Door Front Right // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Front / Logo / Replace-cracked



Front / Calendar / Replace-cracked