

INSPECTION REPORT






End of contract


GENERAL INFO

File	314110
License plate	2CBJ581
Vehicle identification number	VSSZZZKJZNR113407
Dossier	2022 026 030
Make	Seat Arona 1.0 70kW Move
Mileage	100928
First registration	20/05/2022
client availability date	08/06/2026
inspectionDate	10/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	Y
110	Wing Rear Left // Smart Repair Small	Y
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
150	Rear Bonnet // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
187	Wing Rear Right / Trim / Replace	Y
199	Door Rear Right / Window / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
217	Door Front Right / Trim / Replace	Y
219	Door Front Right / Window / Replace	Y
283	Bumper Rear / Trim Right / Replace	N
431	Seat Rear Left // Repair	Y
551	Central Console // Repair	N
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures



Central Console // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Right / Replace-scratch



Bumper Rear // Painting-scratch



Wing Rear Left / Trim / Replace-scratch




Rear Left Door Interior Coating // Repair-scratch




Seat Rear Left // Repair-scratch



Bumper Front // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Door Rear Right / Window / Replace-scratch



Door Front Right / Window / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Left // Smart Repair Medium-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Rear Left // Smart Repair Small-dent



Rear Bonnet // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-cracked



Wing Rear Right / Trim / Replace-bad position