

INSPECTION REPORT

End of contract

GENERAL INFO

File	318035
License plate	2AQP551
Vehicle identification number	TMBJJ7NS0M8062610
Dossier	2021 014 107
Make	Skoda Kod.2.0CRTDI 110kW Cleve
Mileage	142274
First registration	14/06/2021
client availability date	31/07/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
154	Rear Bonnet // Repair & Painting	N
193	Door Rear Right // Painting	Y
213	Door Front Right // Painting	Y

Damage Pictures



Bumper Front / Lower Cover Not Painted / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Right // Painting-scratch



Door Front Right // Painting-scratch



Rear Bonnet // Repair & Painting-scratch + dent



Bumper Front // Polish-stain