

INSPECTION REPORT



End of contract

GENERAL INFO

File	314512
License plate	2EGP467
Vehicle identification number	VR3UPHNKSP5117807
Dossier	2022 363 227
Make	Peugeot 208 1.2PT 100 Active P
Mileage	116835
First registration	04/10/2023
client availability date	04/06/2026
inspectionDate	11/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	Y
153	Rear Bonnet // Painting	Y
163	Roof // Repair & Painting	Y
184	Wing Rear Right // Repair & Painting	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
773	Interior / A Pillar Lower Cover / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Front Right Door Interior Coating // Replace Completely-scratch




Rocker Panel Right // Smart Repair Medium-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Bumper Front // Painting-scratch




Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Wing Front Left // Polish-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch




Rear Bonnet // Painting-scratch




Wheel Rear Right / Wheel Cover / Replace-scratch



Door Rear Right // Smart Repair Small-scratch



Wing Rear Right // Repair & Painting-dent



Roof // Repair & Painting-dent




Door Front Left // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Interior // Repair 1-missing



Interior Cleaning // Small-stain



Trunk Compartment / Side Cover Left / Replace-bad position