

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	284677
License plate	1WDM180
Vehicle identification number	WAUZZZ8V3KA082673
Dossier	2019 052 128
Make	Audi A3SB 30 TDi 85kW
Mileage	201251.00
First registration	03/05/2019
	16/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Front Right // Repair-scratch