

INSPECTION REPORT


End of contract

GENERAL INFO

File	310617
License plate	2BVS147
Vehicle identification number	VF3MRHNSMNS054022
Dossier	2021 351 104
Make	Peugeot 3008 1.2PTech 96kW All
Mileage	79252
First registration	08/04/2022
client availability date	21/04/2026
inspectionDate	22/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
271	Bumper Front / Trim Left / Replace	Y
18	Bumper Front / Spoiler / Replace	N
104	Door Rear Left // Repair & Painting	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
316	Tyre Front Left // Replace	N

Damage Pictures






Damage within Renta-norm-





Light / Rear left / Replace-scratch




Wing Rear Right // Polish-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Wing Rear Left // Smart Repair Small-dent



Door Rear Right // Repair & Painting-dent



Door Rear Left // Repair & Painting-scratch + dent



Tyre Front Left // Replace-tear



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Polish-scratch