

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306816
License plate	1XHY157
Vehicle identification number	W1V4156031U280414
Dossier	2019331164
Make	Mercedes Citan 109CDI L2 Perf.
Mileage	71065
First registration	10/01/2020
client availability date	27/02/2026
inspectionDate	09/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
162	Roof // Painting	N
304	Rear Loading Door Right // Repair & Painting	N
532	Trunk Compartment / Side Cover Left / Replace	N
883	Key Price Range 2 //	N

## Damage Pictures




Damage within Renta-norm-scratch



Rear Loading Door Right // Repair & Painting-scratch + dent



Trunk Compartment / Side Cover Left / Replace-cracked



Roof // Painting-Chemical reaction