

INSPECTION REPORT




End of contract

GENERAL INFO

File	321725
License plate	2DEG130
Vehicle identification number	TMBJP8NX2PY087609
Dossier	2021342095
Make	Skoda Oct.Com.1.0 eTec 81kW Cl
Mileage	152569
First registration	21/02/2023
client availability date	22/09/2026
inspectionDate	29/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
133	Bumper Rear // Painting	N
183	Wing Rear Right // Painting	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	N
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Left // Smart Repair Medium-scratch




Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Door Front Right // Painting-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Painting-scratch



Bumper Rear // Painting-scratch




Rocker Panel Left // Smart Repair Medium-scratch + dent




Bumper Front // Painting-bad repair




Wing Front Left // Painting-bad repair



Windshield // Repair-cracked



Front Bonnet / Insulation / Replace-cracked



Interior Cleaning // Small-stain