

INSPECTION REPORT


End of contract

GENERAL INFO

File	314781
License plate	2BPU870
Vehicle identification number	W1K2938901F041310
Dossier	2021083123
Make	Mercedes EQC 400 4Matic Busine
Mileage	143006
First registration	08/02/2022
client availability date	08/06/2026
inspectionDate	12/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
12	Bumper Front // Smart Repair Large	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
205	Rocker Panel Right // Polish	Y
554	Central Console // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Rocker Panel Right // Polish-scratch





Bumper Rear // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Front Bonnet // Polish-scratch



Wing Front Left // Polish-scratch



Interior / Side Cover rear Seat / Replace-scratch




Central Console // Replace Completely-scratch



Door Rear Left // Painting-bad repair



Wing Rear Left // Painting-bad repair



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Door Rear Right // Polish-scratch



Door Front Right // Polish-scratch