

INSPECTION REPORT


End of contract

GENERAL INFO

File	308528
License plate	2BPL620
Vehicle identification number	YV1XZBBVFN2740494
Dossier	2021 245 037
Make	Volvo XC40 T5 PHEV Inscription
Mileage	136734
First registration	04/02/2022
client availability date	25/03/2026
inspectionDate	27/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	N
186	Wing Rear Right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Wing Rear Left // Repair & Painting-scratch + dent