

INSPECTION REPORT

End of contract

GENERAL INFO

File	309032
License plate	2FXJ833
Vehicle identification number	VR3FRHNS9RY602496
Dossier	2023354020
Make	Peugeot 308 SW 1.2 130 Active
Mileage	29431
First registration	26/09/2024
client availability date	25/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
63	Wing Front Left // Painting	Y
136	Bumper Rear // Polish	Y
165	Roof // Polish	Y
311	Wheel Alloy Front Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
621	Front Right Door Interior Coating // Repair	N


Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Right Door Interior Coating // Repair-scratch



Roof // Polish-scratch



Bumper Rear // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Painting-stone chipping